

Crosby Ravensworth Parish Council

Risk Assessment – Lyvennet Beck flowing through Maulds Meaburn Village Green.

Reviewed by Chairman & Clerk. Approved 10th Oct 22 (097/22)

To be reviewed annually.

Risk Assessment

The Lyvennet Beck runs the whole length of the Village Green in Maulds Meaburn. The Green is grazed by sheep and used for recreational activities. It is owned by the Maulds Meaburn Recreation Ground Trust, Sole Trustee, Parish Council.

<i>Area</i>	<i>Hazards</i>	<i>Potential Outcome / Risk</i>	<i>People at risk</i>	<i>Control Measures</i>	
				<i>Existing</i>	<i>Proposed</i>
Beck generally	Increase in speed and depth of river after heavy or prolonged rain.	Drowning.	Public	None	No further measures Green is common land and cannot be fenced. No known accidents in living memory.
Beck generally	Waterbourne diseases	Infection/illness	Public	Parents to advise	No further measures
Public footpath adjacent to footbridges Riverbank opposite south of the bridge.	Slipping, falling, erosion, landslip	Injuries consistent with falling into water, drowning. Erosion of bank safe standing	Public	Willow planting. Parish Council monitor condition and report any concerns to YDNP Authority.	No further measures
Bridges 2 Road bridges 4 Foot bridges	Climbing onto and falling from bridges	Injuries consistent with falling into water, drowning.	<i>Public</i>	Parish Council monitor condition and report any concerns to National Park Authority.	No further measures
Stepping Stones	Climbing onto and falling from stepping stones	Injuries consistent with falling into water, drowning.	Public	Parish Council monitor condition and report any concerns to	No further measures

Area	Hazards	Potential Outcome / Risk	People at risk	Control Measures	
				Existing	Proposed
				National Park Authority/Environment Agency	
Fish Ladder	Deep water when pools not full of gravel.	Drowning	Small children	Warning notices	No further measures
Overhead electricity cables	People / things coming into contact with cables	Electrocution	Fishermen, kite flyers, people driving tall vehicles or machinery.	Warning notices underneath and either side of cables at each bank of beck	No further measures
Trees	Falling branches or trees	Injury or death	Public,	Trees monitored by specialists at regular intervals	Annual Review specialist adviser
Pumping stations and sewage works, manholes	Falling into manholes	Injury or death Pollution by foul drainage	Public	Report Issues to United Utilities	No further measures
Road	Cars exceeding speed limit	Injury or death	Young children, young cyclists. Especially during times 08:30 to 09:00 and 15:15 to 15:45 on schooldays	Road users to observe speed limit	No further measures